

<h1>AIP SUPPLEMENT - SUOMI / FINLAND</h1> <p>Aeronautical Information Service</p> <p>www.ais.fi</p> <p>Fintraffic ANS, PL 157, FI-01531 VANTAA, ais@fintraffic.fi</p>	<p>AIP SUP NR</p> <p><b>156 / 2024</b></p> <p><b>WEF</b> <b>20 NOV 2024</b></p>
---	---

<b>Aihe</b>	<b>HELSINKI FIR, TILAPÄINEN SUOJAVYÖHYKE (FBZ) FREEZING WINDS 2024</b>		
<b>Subject</b>	<b>HELSINKI FIR, TEMPORARY FLIGHT PLAN BUFFER ZONE FREEZING WINDS 2024</b>		
<b>Voimassaolo Validity</b>	<b>20 NOV 2024 0400 UTC - 29 NOV 2024 1600 UTC</b>		
<b>Aktivointi Activation</b>	WILL BE ACTIVATED BY AUP/UUP: MAX activity times: 20 NOV 2024 0400 UTC - 29 NOV 2024 1600 UTC		
<b>Liikenne- ja viestintäviraston päätös Decision of Finnish Transport and Communications Agency</b>	TRAFICOM/566274/05.00.12.00/2024, 24.10.2024		
<b>AIP REF</b>	ENR 5.1	<b>Julkaisupäivä Publication date</b>	07 NOV 2024
<b>Alueet / Areas</b>			
	<b>Designation Lateral limits</b>	<b>Vertical limits</b>	<b>Remarks</b>
	<b>EFD905AZ SAARISTOMERI 1 FBZ</b> 594451N 0230956E - 593304N 0231907E - 590000N 0210000E - 591524N 0203239E - 592902N 0200745E - 593826N 0203830E - 593434N 0212713E - 593428N 0213143E - 593630N 0221922E - 594154N 0223252E - 594357N 0224933E - 594451N 0230956E	<u>FL 125</u> FL 95	AMC Manageable Area Only for FPL validation
	<b>EFD905BZ SAARISTOMERI 2 FBZ</b> 594944N 0234904E - 594113N 0235551E - 592815N 0225757E - 594346N 0224541E - 594514N 0231857E - 594944N 0234904E	<u>FL 125</u> FL 95	AMC Manageable Area Only for FPL validation
	<b>EFR603AZ SAARISTOMERI 1 FBZ</b> 601338N 0224841E - 595414N 0230601E - 594954N 0230559E - 593655N 0231607E - 593305N 0231048E - 593219N 0225320E - 593104N 0224315E - 592503N 0222810E - 592242N 0213218E - 592250N 0212455E - 592719N 0202830E - 593459N 0202701E - 594432N 0205859E - 595027N 0210819E - 595147N 0210819E - 595854N 0210040E - 600325N 0210456E - 600705N 0214812E - 601338N 0224841E	<u>FL 125</u> FL 95	AMC Manageable Area Only for FPL validation
	<b>EFR603BZ SAARISTOMERI 2 FBZ</b> 595535N 0234426E - 594112N 0235550E - 593331N 0232110E - 593222N 0225442E - 595027N 0224023E - 595416N 0224517E - 595514N 0230646E - 595540N 0231618E - 595535N 0234426E	<u>FL 125</u> FL 95	AMC Manageable Area Only for FPL validation
<b>Huomioitavaa</b>	Seuraavissa AUP/UUP:ssa aktiiviseksi ilmoitetuissa FBZ:issa suojavyöhykkeeseen sisältyy myös siihen liittyvä R-alue: EFR603A, EFR603B. Tämän vuoksi AUP/UUP:ssa FBZ:n alaraja vastaa TEMPO R-alueen eikä FBZ:n AIP Supplementissa julkaistua alarajaa.  Tämä AIP SUP julkaisu sisältää xml-siirtotiedoston AIXM 5.1 muodossa julkaistujen alueiden sivu- ja korkeusrajoista. Lisätietoja AIP Supplementtien AIXM-liitetiedoista löytyy AIC-tiedotteesta ( <a href="https://www.ais.fi/ais/aica/AipAicA.htm">https://www.ais.fi/ais/aica/AipAicA.htm</a> ).		
<b>Remarks</b>	In the following FBZs that are activated by AUP/UUP the buffer zone includes also the related TEMPO R: EFR603A, EFR603B. Therefore the lower limit of the FBZ in AUP/UUP equals the lower limit of TEMPO R area not the lower limit of the TEMPO FBZ published by AIP Supplement.  This electronic AIP SUP publication contains xml-file attachment in AIXM 5.1 format. More information related to AIP Supplement AIXM attachments can be found in AIC ( <a href="https://www.ais.fi/ais/aica/AipAicA_en.htm">https://www.ais.fi/ais/aica/AipAicA_en.htm</a> ).		

# TEMPORARY FLIGHT PLAN BUFFER ZONE FREEZING WINDS 2024

