

AIP SUPPLEMENT - SUOMI / FINLAND

Aeronautical Information Service

www.ais.fi

ANS Finland, PL 157, FI-01531 VANTAA, ais@ansfinland.fi

AIP SUP NR
28 / 2018

AIRAC

WEF
26 APR 2018

TAMPERE-PIRKKALAN LENTOASEMA, RAJOITUKSET JA TILAPÄISET JÄRJESTELYT TYÖVAIHEEN 2 AIKANA 30.4. - 14.5.2018

Julkaisupäivä 15.3.2018

Kiitotien päällystystyöt alkavat. Tällä Supplementilla on julkaistu työvaiheen 2 aikana voimassa olevat rajoitukset.

1. Aika

30 APR 2018, 0400 UTC - 14 MAY 2018, 0500 UTC

2. Rajoitukset

Työalue ja muut liikenteeltä suljetut alueet on esitetty sivun 3 piirroksessa.

2.1 Kiitoteiden käytettävyys

Kiitotie 06/24 ei ole käytössä.
Työvaiheen aikana on käytössä **kiitotie 06/24C**.

THR 24 ei ole käytössä.
Työvaiheen aikana on käytössä **THR 24C**.

2.2 Rullaustiet

Rullaustiet F ja G ovat suljettuna liikenteeltä.

2.3 Ilma-alusten seisontapaikat

Seisontapaikat A4, A5, A6, B1 ja B2 eivät ole käytössä.

Tilapäinen seisontapaikka **TEMPO A4** on käytössä (612509.90N 0233653.58E, PCN 50/F/A/W/T).

2.4 Odotuspaikat

Odotuspaikka D ei ole käytössä.

Tilapäinen odotuspaikka D on käytössä ja merkitty kyltein.

3. Merkinnät

3.1 Kiitotien liikenteeltä suljettu osuus on merkitty valoras-teilla.

3.2 Työmaa-alue on merkitty lipuilla, keiloilla ja punaisilla valoilla.

TAMPERE-PIRKKALA AERODROME, RESTRICTIONS AND TEMPORARY ARRANGEMENTS DURING WORKING PHASE 2 FROM 30 APR TO 14 MAY 2018

Publication date 15 MAR 2018

The resurfacing work begins. Restrictions during phase 2 are published in this Supplement.

1. Period

30 APR 2018, 0400 UTC - 14 MAY 2018, 0500 UTC

2. Restrictions

The working area and other areas closed to traffic are shown in the sketch on page 3.

2.1 Runway availability

Runway 06/24 is not in use.
Runway 06/24C is in use during the working phase.

THR 24 is not in use.
THR 24C is in use during the working phase.

2.2 Taxiways

Taxiways F and G are closed to traffic.

2.3 Aircraft stands

Stands A4, A5, A6, B1 and B2 are not in use.

Temporary stand **TEMPO A4** is in use (612509.90N 0233653.58E, PCN 50/F/A/W/T).

2.4 Holding positions

Holding position D is not in use.

Temporary holding position D is in use and marked with signs.

3. Markings

3.1 The closed portion of the runway is marked with lighted aids.

3.2 The working area is equipped with flags, cones and temporary lights (R LIL).

4. Mittarilaskeutumislaitteet

RWY 24 ILS GP ja LOC eivät ole käytössä.

5. Kartat ja lentomenetelmät

5.1 **EFTP AOC RWY 06/24** ei ole käytössä.

5.2 **Vaikutukset lähtö- ja lähestymismenetelmiin** julkaistaan NOTAMilla.

5.3 Työvaihetta varten on käytössä seuraavat erikseen julkaistut **kartat ja menetelmät**:

EFTP AOC RWY 06/24C
EFTP RNAV SID RWY 24C
EFTP RNAV STAR RWY 24C
EFTP RNAV (GNSS) RWY 24C
EFTP VOR RWY 24C

Päällystystyöt jatkuvat. Rajoitukset ja tilapäiset järjestelyt julkaistaan erillisillä Supplementeilla.

4. Instrument approach facilities

RWY 24 ILS GP and LOC are not in use.

5. Charts and instrument approach procedures

5.1 **EFTP AOC RWY 06/24** is not in use.

5.2 **The impact to departure and approach procedures** will be published by NOTAM.

5.3 The following published **charts and procedures** are valid for the working phase:

The resurfacing work continues. Restrictions and temporary arrangements will be published by a separate Supplements.

TAMPERE-PIRKKALA AD
RAJOITUKSIA JA TILAPÄISIÄ JÄRJESTELYJÄ / RESTRICTIONS AND TEMPORARY ARRANGEMENTS
30 APR - 14 MAY 2018

